Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2262 Work Order Type: Weatherization **Audit Name: 14014SO2262**

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2262 MANCHESTER, TN 37355

Alt. Client ID: COFFEE

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY **Agency Phone:** (931) 433-7182 Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

> FAYETTEVILLE, TN 37334-2001 Email Address: e.satterfield@schra.us

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client Name: Client ID: 14014SO2262 Alt. Client ID: COFFEE

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: 14014SO2262 Version 8.5.0 Report Run On: 5/14/2010 Page 1 of 3

Measure 1 Inf	iltration Redctn			Componen	ts			Inspected
	DUCT WORK / SEAL REG TO REDUCE CFM'S BY 4		WITH	MASTIC / IN	NTERIOR	AIR		
				Estimated	1	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Supplies	Infiltration Reduction	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
Measure 2 Att	tic Ins. R-30			Componen				Inspected
				Estimated			Actual	Inspected
	tic Ins. R-30 Description / Comment	Units	Qty	•		Qty		Inspected Total
Comment		<i>Units</i> SqFt		Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor	Description / Comment Attic Insulation - Blown		Qty	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	SqFt	Qty 1232	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	SqFt	Qty 1232	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	SqFt	Qty 1232	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	SqFt SqFt	Qty 1232 1232	Estimated	<u> </u>		Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	SqFt SqFt	Qty 1232 1232	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	SqFt SqFt	Qty 1232 1232	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment Attic Insulation - Blown Cellulose - R-30 Attic Insulation - Blown	SqFt SqFt	Qty 1232 1232	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Report Run On: 5/14/2010

Measure 3 Smoke Detector is Needed				Componen	ts	Inspected				
C	omment									
				Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Smoke / Carbon detector	Each	1						
2	Labor	Labor	Hour	1						
(Other Detail						-			
Measure Sub Total: Sub Total:										
	Field Notes:									
		Work Order Grand Total: Grand Total:								